

Product Safety Recall



Kubota RTV-X Series Utility Vehicles

RTV-X900 (serial nos. 31229 - 42402)

RTV-X1100 serial nos. 26899 - 35995)

RTV-X1120 (serial nos. 18541 - 20746)

RTV-X1140 (serial nos. 10001 - 19546)

- Defect:** Repetitive bending stress during operation of the vehicles may cause the thin plate seat belt stay to fracture and it may not satisfy the strength required for the seat belt to hold secure the vehicle operator or passenger.
- Hazard:** If the seat belt stays fracture, there is a risk that the seat belt may release, putting the operator or passenger at risk of injury.
- What to do:** Owners of affected vehicles should stop using the vehicles. Owners will be contacted by Kubota at their warranty-registered address and asked to schedule a time to return vehicles to their nearest Kubota dealership for replacement of the seat belt stays, free of charge.
- Contact details:** Further information is available from your nearest authorised Kubota dealership or from Kubota Tractor Australia on 03 9394 4400 or from www.kubota.com.au.

**See productsafety.gov.au for
Australian product recall information**